1. #1, #2, #3, #4, Roxbury Fish Hatchery
2. Washington, Vermont
3. Ann Cousins
4. January, 1993
5. Vt. Division for Historic Preservation
6. View looking South. (l. to r.) #3 Carriage Barn #2 Ice Meat and Cook House, #1 Hatchery Building #4 Ponds.

Photograph #1

1) #1 Hatchery Building, Roxbury Fish Hatchery
2) Washington, Vermont
3) Ann Cousins
4) January 1993
5) Vermont Division for Historic Preservation
6) View looking southwest, #1 Hatchery Building

Photograph #2

1) #1 Hatchery Building, Roxbury Fish Hatchery
2) Washington, Vermont
3) Ann Cousins
4) January, 1993
5) Vermont Division for Historic Preservation
6) Interior of Hatchery Building

Photograph #3

1) #2. Ice, Meat and Cook House, Roxbury Fish Hatchery

2) Washington, Vermont

3) Ann Cousins

4) January 1993

5) Vermont Division for Historic Preservation

6) View looking Northeast, #2 Ice Meat and Cook House, #3 Carriage Barn in background

Photograph #4

1) #3 Carriage Barn, Roxbury Fish Hatchery
2) Washington Co., Vermont
3) Ann Cousins
4) January, 1993
5) Vt. Division for Historic Preservation
6) View looking Southeast, #3 Carriage Barn

Photograph #5

1) #8 CCC Barn, Roxbury Fish Hatchery
2) Washington Co. Vermont
3) Ann Cousins
4) January 1993
5) Vermont Division for Historic Preservation
6) View looking Northwest, #8 CCC Barn

Photograph #6

VERMONT
FISH & WILDLIFE DEPT.
STATE RESEARCH LAB
ROXBURY VERMONT

1) #10 State Biology Research Lab, Roxbury Fish Hatchery

2) Washington Co., Vermont

3) Ann Cousins

4) January 1993

5) Vt. Division for Historic Preservation

6) View looking Southwest, #10 State Biology Research Lab

Photograph # 7

#11 Shed Roxbury Fish Hatchery
Washington Co. Vermont
Ann Cousins
January 1993
Vt. Division for Historic Preservation
View looking Northwest, #11 Shed, Central
Vermont Railroad tracks in background

Photograph #8